


**BUILDING AND STANDARDS COMMISSION
STAFF REPORT**

July 28, 2014



Case # 2031 – 209 Dellwood Street



LEGAL DESCRIPTION: Miltree Place, Lot 5

STRUCTURE(S):

- single-family residence
- multi-family residence
- mixed use
- commercial
- accessory structure(s)

PROPERTY OWNER(S): Godinez, Luis

LIENHOLDER(S)/

MORTGAGEE(S): none

IMPROVEMENT VALUE(S)

**(AS APPRAISED BY THE
BRAZOS COUNTY**

APPRAISAL DISTRICT): \$48,300 (2014 tax year)

BACKGROUND:

In June 2012, City staff received an application for a utility turn on for this home, which was built in 1945 according to Brazos County Appraisal District records. BTU staff declined to connect electricity due to the dilapidated condition of the home and notified the Fire Marshal's office. An inspection by the Fire Marshal and a City Building Inspector revealed that the electrical panel is in need of repair, the house has structural issues, the yard was overgrown and littered with trash and debris, and multiple abandoned or inoperable vehicles were stored on the lot. The property owner was advised in writing at that time that utilities were being held until he would agree to meet with staff to discuss a plan for repair of the structure. The owner never responded to the 2012 notice. In late 2013, staff received a complaint about the property, whose overall condition and appearance appeared to have further deteriorated since the previous City staff inspection, from a neighboring property owner.

Notices were mailed to the property owner on May 19 and July 2, 2014. In light of the citizen complaint and since the property owner never responded to notices from City staff, the Chief Building Official requested that the property be scheduled for consideration by the Commission.

ATTACHMENTS:

- (1.) staff recommendation
- (2.) pictures
- (3.) dangerous structures survey reports

**BUILDING AND STANDARDS COMMISSION
STAFF RECOMMENDATION**



July 28, 2014

Case #: 2031

Building Address: 209 Dellwood Street

Record Owner(s): Godinez, Luis

The City's Chief Building Official has requested this Commission hearing to discuss the on this property, and all legal notices of the hearing were provided to record owners, lienholders, and mortgagees. They were also notified that if they wanted to repair the building they needed to meet with City staff and come to the hearing with a detailed plan for repairs, including cost estimates. Based on the surveys, reports, photographs, and other evidence provided to the Commission, the City recommends that the Commission find the building unsafe based on the standards set forth in Bryan Code of Ordinances Section 14-224 subsection(s):

- 1) The building, structure, or any part thereof is likely to partially or fully collapse.
- 2) The structure or any part thereof was constructed or maintained in violation of any provision of the City's Building Code, or any other applicable ordinance or law of the city, county, state or federal government.
- 3) One or more walls or other vertical structural members list, lean, or buckle to such an extent that a plumb line passing through the center of gravity falls outside of the middle third or its base.
- 4) The foundation or the vertical or horizontal supporting members are twenty five percent (25%) or more damaged or deteriorated.
- 5) The non supporting coverings of walls, ceilings, roofs, or floors are fifty percent (50%) or more damaged or deteriorated.
- 6) The structure has improperly distributed loads upon the structural members, or they have insufficient strength to be reasonably safe for the purpose used.
- 7) The structure or any part thereof has been damaged by fire, water, earthquake, wind, vandalism, or other cause to such an extent that it has become dangerous to the public health, safety and welfare.
- 8) The structure or any part thereof has inadequate means of egress as required by the City's Building Code.
- 9) The structure does not have adequate light ventilation, or sanitation facilities as required by the City's Building Codes and Plumbing Code.

The City further recommends that the Commission find that:

- the building is unsecured and must be boarded up and/or fenced in such a manner to prevent unauthorized entry by a person, including a child, through missing or unlocked doors or windows or through other openings into the building.**
- the building may not be feasibly repaired in compliance with City ordinances.**

The City recommends that the Commission issue an order to the owner, lienholder, or mortgagee to:

- demolish the building and remove the debris within 30 days.**

The City recommends that the Commission orders that the City may:

- disconnect water and electric utilities to the building; and**
- secure the structure, demolish the building and remove the debris in accordance with Chapter 14 of the City of Bryan's Code of Ordinances if the owner, lienholder, or mortgagee fails to comply with the Commission's order.**

PICTURES: 06-10-14





Attached Garage



Lean-to





Dangerous Structures Survey Report

Chief Building Official

Case # 2031

A. PROPERTY ADDRESS: 209 Dellwood Street, Miltree Place, Lot 5

B. SPECIFICATIONS: No. Rooms 10[±] No. Stories 1 No. Structures 1

STRUCTURAL USE

CONSTRUCTION

OCCUPANCY

- Residential/Single Family
- Mixed Use
- Commercial
- Residential/Multi Family
- Accessory Structure(s)

- Box
- Frame
- Masonry
- Mobile Home

- Occupied
- Vacant
- Open

C. FINDINGS

01. The structure or a part thereof was constructed or maintained in violation of a provision of the City's building code, other applicable ordinance, state law, or federal law. Specifically, the following:

2009 IRC

Main structure? Accessory structure?

02. Any wall or other vertical structural members list, lean, or buckle to an extent that a plumbline passing through the center of gravity falls outside of the middle third of its base. Main structure? Accessory structure?

03. The foundation or the vertical or horizontal supporting members are materially damaged or deteriorated. Main structure? Accessory structure?

04. The non-supporting coverings of walls, ceilings, roofs, or floors are materially damaged or deteriorated. Main structure? Accessory structure?

05. The structure has improperly distributed loads upon the structural members, or they have insufficient strength to be reasonably safe for the purpose used. Main structure? Accessory structure?


06. The structure or any part thereof has inadequate means of egress as required by the city's building code. Main structure? Accessory structure?

07. The structure is unsanitary, unfit for human habitation, or likely to cause sickness due to damage, deterioration, or inadequate design/construction. Specifically the structure does not meet the city's requirements for:

- light
- ventilation
- sanitation facilities

Main structure? Accessory structure?

D. FLOOR PLAN (if necessary)



E. DETERMINATION

1. It has been determined upon inspection and investigation that the structure is dangerous, unsafe, or a hazard to public health and must be secured and:

A. Be vacated OR remain unoccupied; and

B. Be repaired OR be demolished.

2. It has been determined upon inspection and investigation that the structure is not dangerous, unsafe, or a hazard to public health as defined by the City's Code of Ordinances.

Craig Teppa
Signature

Craig Teppa
Printed Name

6/19/2014
Date



CITY OF BRYAN
The Good Life, Texas Style

Dangerous Structures Survey Report

Fire Marshal

Case # 2031

A. PROPERTY ADDRESS: 209 Dellwood Street, Miltree Place, Lot 5

B. SPECIFICATIONS: No. Rooms _____ No. Stories _____ No. Structures 1

STRUCTURAL USE

- Residential/Single Family
- Mixed Use
- Commercial
- Residential/Multi Family
- Accessory Structure

CONSTRUCTION

- Box
- Frame
- Masonry
- Mobile Home

OCCUPANCY

- Occupied
- Vacant
- Open

C. FINDINGS

- 01. The structure or a part thereof has been damaged by fire, water, earthquake, wind, vandalism, or other cause to such an extent that it has become dangerous to the public health, safety, and welfare.
I estimate that 100% of the main structure is considered a loss.
I estimate that 0% of the accessory structure is considered a loss.
- 02. The structure or a part thereof has deteriorated to such an extent that it has become dangerous to the public health, safety, and welfare.
Main Structure? Accessory Structure?
- 03. The structure or a part thereof does not have adequate means of egress as required by the City's building code, and poses a danger in case of fire or panic.
Main Structure? Accessory Structure?
- 04. The structure or a part thereof lacks necessary fire-resistive construction, and the threat of a fire in the structure poses a risk to inhabitants, neighboring structures, and fire department personnel.
Main Structure? Accessory Structure?
- 05. Obsolete, damaged, or deteriorated electric wiring, gas connections, heating apparatus, or other mechanical infrastructure present a risk of fire.
Main Structure? Accessory Structure?
- 06. The proximity of the structure or a part thereof to other structures on this or neighboring properties constitutes a fire hazard for the other structures.
Main Structure? Accessory Structure?
- 07. The structure or a part thereof is in violation of the City's fire code.
Main Structure? Accessory Structure?

08. The building, structure, or a part thereof is being used by criminals, vagrants, or squatters for the purpose of suspected illegal activity.
Main Structure? Accessory Structure?

09. The building, structure, or a part thereof presents an attractive nuisance to children.
Main Structure? Accessory Structure?

COMMENTS Road Sinking in
holes rotted through floor
open ceilings
open electrical

D. DETERMINATION

1. It has been determined upon inspection and investigation that the structure is dangerous, unsafe, or a hazard to public health and must be secured and:

A. Be vacated OR remain unoccupied; and

B. Be repaired OR be demolished.

2. It has been determined upon inspection and investigation that the structure is not dangerous, unsafe, or a hazard to public health as defined by the City's Code of Ordinances.


Signature

FRED TAYLER / DGM
Printed Name/Title

6-10-14
Date